



DEPARTMENT OF
WATER RESOURCES

UPPER SACRAMENTO AREA *Fact Sheet* **Site 164.0**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento

River Mile: 164.0

Latitude/Longitude:

39.406888/-122.008349

Nearest Impact Area:

Princeton/Colusa

County: Colusa

Bank: Right

Type of Damage

Bank erosion

Length of Repair



800 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources



**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov